

Crown Point Community School Corporation Winfield Elementary Additions & Renovations

Board Report August 23, 2021



Crown Point Community School Corporation Winfield Elementary Additions & Renovations

Board Report

August 23, 2021



Table of Contents

- **Progress Key Plan**
- **Narrative/Update**
- **Progress Photos**
- **Master Schedule**

Progress Key Plan


August 23, 2021

New Gymnasium/Administration Office

Existing Classroom Renovations (Unit A)


Cafeteria/Existing Classroom

Renovations (Unit B)



Classroom Addition/Existing
Classroom Renovations (Unit C)

Classroom Expansion/Existing
Classroom Renovations (Unit D)



Construction Progress Report

Crown Point Community Schools – Winfield Elementary Additions & Renovations

August 23, 2021



**Past 4
Weeks**

Structural/Interiors:

- Completed installing casework and countertops at remaining classrooms.
- Completed installing asphalt and sidewalks throughout the entire site.
- Continued roof work at remaining areas.
- Installed metal panels throughout perimeter.
- Completed installing ceiling grid and tile at remaining classroom areas.
- Continued remaining EIFS work at the exterior perimeter.
- Completed installing floor finishes at remaining renovated areas.
- Completed painting throughout remaining classrooms.
- Painted mural in cafeteria.
- Completed plumbing, mechanical, and electrical trim work throughout.

Construction Progress Report

Crown Point Community Schools – Winfield Elementary Additions & Renovations

August 23, 2021



**Next 4
Weeks**

Structural/Interiors:

- Install Playground Equipment and Soft surface.
- Complete roof work at remaining areas.
- Install coping throughout the building perimeter.
- Complete installing floor base at corridors.
- Complete touchup painting throughout.
- Complete punch list items throughout.
- Complete electrical grounding.
- Complete electrical rough in associated with Technology items.



Progress Photographs



New Entrance



Progress Photographs



New Administration Office



Progress Photographs



Main Corridor



Progress Photographs



Renovated Classroom



Progress Photographs



Renovated Classroom



Progress Photographs



Typical Restroom



Progress Photographs



LGI/Flex Room



Progress Photographs



Media Center



Progress Photographs



Music Room



Progress Photographs



Cafeteria

